

This notice is to inform building occupants of the status, condition, presence and location of asbestos containing materials (ACM) within our facilities. We routinely monitor the condition of ACM present in our facilities to ensure it is not damaged. Damaged material is abated and replaced with Asbestos Free materials if possible or repaired. The 2006 Asbestos Surveillance inspection found ACM in our facilities to be in good condition. Currently ACM in our facilities is found in some pipe insulation and chases, floor tile adhesive, acoustical plaster. For information on specific locations of ACM please contact the Facility Management office on 576-0586. For more information about asbestos, please see the OSHA fact sheet at http://www.osha.gov/OshDoc/data_AsbestosFacts/asbestos-factsheet.pdf.